






$Z = 100\text{mm}$



$Z = 120\text{mm}-140\text{mm}$







3-10mm










10-15mm





Z = 100mm






4



5



45 - 90mm



15 - 45mm




10 - 15mm




7,8,9,10mm



6a




7b




6b


3,4,5,6mm




7b




8




9




10







11






12







17






4x  
30mm

18




19






25



26



27

